

JOB SUMMARY

Customer	XXXX		
Location	XXXXX		
Name of Work	Visual & Thermal Inspection		
Document Number	Xxx - 001	Asset Name	Switchyard
Inspection Date	XXXX	Weather	Haze
Inspection Time	Day Time	Ambient Temperature	27° C
Inspection Type	Visual & Thermal Inspection	Equipment Used	Mavic 3 Thermal
Prepared By	Muthukumar U		

OVERVIEW

Major Observations:

1. No anomalies were found


NOTE:

- The altitude that we mention in the observations has $\pm 1\text{m}$ difference.

Recommendations:

1. No major anomalies found, So no recommendations.

XXXX




Source Image:

DJI_20241115123743_0001_V&T

Visual Observations:

- No anomalies were found.

XXXX




Source Image:

DJI_20241115123746_0003_V&T

Visual Observations:

- No anomalies were found.

XXXX




Source Image:

DJI_20241115123749_0005_V&T

Visual Observations:

- No anomalies were found.

XXXX




Source Image:

DJI_20241115123750_0006_V&T

Visual Observations:

- No anomalies were found.

XXXX



Source Image:

DJI_20241115123804_0015_V&T

Visual Observations:

- No anomalies were found.